

1/12




FIG.1

2/12





FIG.2


3/12

FIG.3A




↓ INCREASING TRANSPARENCY  
BY HIGH TEMPERATURE

FIG.3B




↓ RIE

FIG.3C




↓ FHD

FIG.3D



↓ INCREASING TRANSPARENCY  
BY HIGH TEMPERATURE

FIG.3E



4/12




FIG.4

5/12




FIG.5

6/12




FIG.6

7/12




FIG.7

8/12




FIG.8



9/12




FIG.9

10/12




FIG.10

11/12




FIG.11

12/12




FIG.12